

Guild of Devonshire Ringers - Library Catalogue: Bell installations & Maintenance (June 2024)

Accn No.	Author	Title	Edn	Pages	Publisher	Date	ISBN	Shelf	E-copy
12/0126	Beech, Frank	Splicing bell ropes illustrated: give your ropes a new life		32	CCCBR	2005	0900271825	TECHp	
R/0387	CCCBR	A handbook on the preservation and repair of bells, bell-frames and fittings and other kindred matters	2nd	34	CCCBR	1930		TECHp	
09/0006	CCCBR: Towers and Belfries Committee	Towers and bells: A handbook	2nd	119	CCCBR	1990	0-900271175	TECH	
09/0021	CCCBR: Towers and Belfries Committee	The towers and bells handbook		64	CCCBR	1973		TECH	
17/0174	CCCBR: Towers and Belfries Committee	Manual of belfry maintenance		126	CCCBR	2017	9781911210016	TECH	
R/0260	CCCBR: Towers and Belfries Committee	Towers and bells: A handbook	2nd	119	CCCBR	1990	0-900271175	TECH	
09/0239	CCCBR: Towers and Belfries Committee	A schedule of regular maintenance		19	CCCBR	1991	0900271211	TECHp	
09/0240	CCCBR: Towers and Belfries Committee	A handbook on the installation, preservation, and repair of bells, bell-frames and fittings and other kindred matters	5th	26	CCCBR	1962		TECHp	
R/0390	CCCBR: Towers and Belfries Committee	A schedule of regular maintenance		19	CCCBR	1991	0900271211	TECHp	
R/0392	CCCBR: Towers and Belfries Committee	The bell adviser		12	CCCBR	1989		TECHp	
09/0011	Clouston, R.W.M.	A practical guide to the inspection of church bells		42	The author	[197-]		TECH	
09/0026	Council for the Care of Churches	The conservation and repair of bells and bellframes		27	The Council	1993	0715175653	TECHp	

Accn No.	Author	Title	Edn	Pages	Publisher	Date	ISBN	Shelf	E-copy
09/0040	Council for the Care of Churches	Turret clocks: automatic winders and electric drives. A document prepared by the Clocks Sub-committee		5	The Council	1984		TECHp	
09/0041	Council for the Care of Churches	Turret clocks: Recommended practice for repair and maintenance of turret clocks in churches. A document prepared by the Clocks Sub-committee		12	The Council	1982		TECHp	
09/0220	Council for the Care of Churches	Turret clocks: Recommended practice for repair and maintenance of turret clocks in churches. A document prepared by the Clocks Sub-committee		12	The Council	1982		TECHp	
R/0292	Heuven, E.W. van	Acoustical measurements on church-bells and carillons		156	Gebroeders van Cleef	1949		TECH	
R/0350	Heywood, Arthur Percival	Bell towers and bell hanging: An appeal to architects		184	Longman & Green	1914		TECH	Whiting Society
R/0274	Jennings, Trevor S	Bellfounding		32	Shire Pubns	1988	0852639112	TECH	
R/0416	Johnston, Cyril F.	Bells old and new: The antiquary, the 3rd bellfounder and the Church		20	The author	1929		TECHp	
09/0029	Pickford, Chris	Bellframes: A practical guide to inspection and recording		60	The author	1993	0951232118	TECH	
12/0124	Robinson, D.J. & Windsor, H.M.	A practical analysis of the interaction between church bells and towers		67	CCCBR	1994	0900271319	TECH	
09/0030	Robinson, D.J. & Windsor, H.M.	Tower deflection at Coventry Cathedral		64	Coventry Diocesan Guild	1985		TECHp	
09/0238	W.J. Furse & Co.	Earthing and lightning protection equipment		55	Furse & Co.	1992		TECH	